


Комод 036 Пенни






















Прежде чем приступить к сборке, ознакомьтесь с памяткой на обороте





- | | | | |
|-----------|------------------------------------|-----------|--------------------------------|
| D | Montageanleitung | GB | Assembly instructions |
| FR | Notice de montage | IT | Istruzioni di montaggio |
| NL | Handlieding voor de montage | PL | Instrukcja montażu |
| CZ | Montážní návod | SK | Návod na montáž |
| HU | Szerelési útmutató | RO | Instrukțiuni de montaj |
| TR | Montaj talimatı | RU | Инструкция по монтажу |






№	Size/MaB (mm)	Qty	✓	№	Size/MaB (mm)	Qty	✓
1	1444x452x24	1		15	160x50x50	2	
2	762x435x50	1		16	160x50x50	1	
3	762x435x50	1		17	420x120x18	3	
4	612x369x18	1		18	350x100x14	3	
5	1310x45x24	1		19	350x100x14	3	
6	1370x45x24	1		20	390x100x14	3	
7	126x369x18	2		21	399x342x3	3	
8	1310x76x18	1		22	641x200x18	6	
9	276x31x24	8		23	350x150x14	6	
10	1420x440x18	1		24	350x150x14	6	
11	335x50x18	2		25	611x150x14	6	
12	1310x68x18	1		26	620x342x3	6	
13	1310x40x18	1		27	1328x390x3	1	
14	160x50x50	2		28	1328x390x3	1	






5



B 030110
x6



6




B 030110
x22




O 030033
7x50
x7




P 110022
SW 4
x1

7



I 220043
x4



8

A 030093
x30


B 030110
x30

C 230010
8x32
x60


R 210020
x15

S 030052
M4x22
x15

L 250024
3.5x35
x18



x3



x6

9

E 030043
M4x10
x18

V 180080
x2

V1 090004
x2

V2 250012
3.5x15
x2

V3 250044
4x40
x2

