

D Montageanleitung

FR Notice de montage

NL Handleiding voor de montage

CZ Montážní návod

HU Szerelési útmutató

TR Montaj talimatı

GB Assembly instructions




IT Istruzioni di montaggio

PL Instrukcja montażu

SK Návod na montáž


RO Instrucțiuni de montaj



RU Инструкция по монтажу



1-9

EAC








No	Size/MaB (mm)	Qty	✓	No	Size/MaB (mm)	Qty	✓
1	1078x489x18	1		20	1965x40x40	1	
2	489x489x18	1		21	735x161x18	1	
3	853x50x24	1		22	684x40x18	1	
4	432x50x24	1		23	689x140x14	1	
5	432x50x24	1		24	698x302x3	1	
6	837x416x18	1		25	1131x502x3	1	
7	1851x320x15	1		26	1131x256x3	1	
8	1851x320x15	1		27	760x193x3	1	
9	1120x377x15	1		28	502x256x3	1	
10	741x377x15	1		29	502x502x3	1	
11	740x36x18	1		30	302x206x3	3	
12	239x373x15	3		31	243x161x18	3	
13	740x36x18	2		32	197x140x14	3	
14	741x57x15	1		33	486x377x15	1	
15	741x57x15	1		34	485x373x15	4	
16	741x382x15	1		35	310x140x14	4	
17	1965x40x40	1		36	310x140x14	4	
18	1965x40x40	1		37	738x17x7	1	
19	1965x40x40	1					

1

A 030093 x32

C 230010 8x32 x12

M 070017 30x30 x4



2

B 030110 x20







G 250016 3,5x20 x10

H 050022 x10

J 250012 3,5x15 x10

Q 180030 x5

T 160018 x5





3

A 030093 x6

C 230010 8x32 x22



J 250012 3,5x15 x6

T 160018 x3





4

B 030110 x6



5



U 220015
L=15MM x2



6

O 030033
7x50 x2


R 110022
SW4 x1




7


O 030033
7x50 x4

R 110022
SW4 x1





8


B		030110
		x12





9

V		230011
8x20		x2

O		030033
7x50		x6



R		110022
SW4		x1

K		250024
3,5x35		x6







10

N 220043
1,2x20 x4




- | | | | | | | |
|-----------|------------------------|------------------------|-----------------------------|-----------------------------|-----------------------|------------------------------|
| 11 | A 030093
x16 | B 030110
x16 | C 230010
8x32 x24 | D 030052
M4x22 x5 | F 210131
x5 | K 250024
3,5x35 x8 |
|-----------|------------------------|------------------------|-----------------------------|-----------------------------|-----------------------|------------------------------|

- | |
|------------------------------|
| L 250021
3,5x30 x4 |
|------------------------------|



- | | | | | |
|-----------|-----------------------------|-----------------------|-------------------------------|-----------------------|
| 12 | D 030052
M4x22 x2 | F 210131
x2 | J 250012
3,5x15 x10 | P 180049
x5 |
|-----------|-----------------------------|-----------------------|-------------------------------|-----------------------|



13

E 030043
M4x10 x8

S 190002
x28

Y1 090004
8x40 x1

Y2 180080
x1

Y3 250012
3,5x15 x1

Y4 250044
4x40 x1

